

**To:** Singhvi, Raj[Singhvi.Raj@epa.gov]; DOnofrio, Cris[DOnofrio.Cris@epa.gov]; Garrison, Geoffrey[Garrison.Geoffrey@epa.gov]  
**From:** Daloia, James  
**Sent:** Thur 4/16/2015 11:17:44 AM  
**Subject:** Hummm.... Still trying to clear the building of MB????

Hey guys: I read Jimenez's last polrep,"removing all porous surfaces"? I had explained a while ago after speaking to some industry experts that this material unlike Chlorine Dioxide and VHP was going to have a much greater residency time inside a structure like this. Constant mechanical ventilation and possible wipe decon may be necessary on certain surfaces like leather goods. I heard that the building was closed up for a period of time in between the time that Cris left and now? I assume we are using no detect as an interim clearance level, until ATSDR can provide further guidance, good luck on that one. Anyway I wanted to let you know I was still alive and kicking, from home.